


Coyote Creek- Locations with < 100 Year Capacity
See table for channel capacity
1
2
3
4
5
6
7
8
9
10
11
12
13
San Jose
East Foothills
Alum Rock
Lake Cunningham Park
Los Lagos Golf Course
Spartan Stadium
Coyote Creek Park
Kelley Park
Hellyer County Park
Almaden Lake Park
Golf Club at Boulder Ridge
TJ Martin Park
Almaden Plaza
Westfield Oakridge
Reid-Hillview Airport
San Jose Municipal Golf Course
San Jose Country Club
Job Corps
The Plant
Doerr Park
Watson Park
Alum Rock Park
Cataldi Park
Silver Creek Valley Country Club
SANTA CLARA VALLEY
Sinclair Fwy
Baysh ore Fwy
Guadalupe Pkwy
Almaden Expy
Capitol Expy
Monterey Rd
Norman Y Mineta Hwy
Alum Rock Ave
E Hedding St
E Santa Clara St
Mabury Rd
Berryessa Rd
Story Rd
Tully Rd
Quimby Rd
Aborn Rd
Yerba Buena Rd
Hillsdale Ave
Blossom Hill Rd
Calero Ave
Chynoweth Ave
Branham Ln
Almaden Rd
Curtner Ave
W Alma Ave
W San Carlos St
Silver Creek
Coyote Creek
Los Gatos Creek
Guadalupe River
Dry Creek
Penitencia Creek
Thompson Creek
Sunnydown Ln
Attachment 2
Page 1 of 3
Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community


Coyote Creek- Locations with <100 Year Capacity
See table for channel capacity
14
15
16
17
Coyote
Morgan Hill
SANTA CLARA VALLEY
Monterey Rd
Cochrane Rd
Tulare Hill
Pigeon Point
Santa Teresa Golf Club
Coyote Creek Golf Club
Calero Reservoir County Park
Cinnabar Hills Golf Club
Chesbro Reservoir Park
Anderson Lake County Park
Motorcycle County Park
Field Sports County Park
Historic El Camino Real
Santa Teresa Blvd
Richmond Ave
Dougherty Ave
Palm Ave
Kalana Ave
Hale Ave
Laguna Ave
Dailey Ave
Avenida Espana
Foxsum Rd
Willow Springs Rd
Llagas Rd
Butterfield Blvd
Diana Ave
W Dunne Ave
Dewitt Ave
Paradise Valley
Chesbro Lake Dr
Oak Glen Ave
Manzanita Ridge
Coyote Creek
Llagas Creek
Little Uvas Creek
Paradise Creek
Sycamore Dr
W Edmundson Ave
Watsonville Rd
Jarvis Dr
Condit Rd
E Dunne Ave
La Crosse Dr
Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Coyote Creek- Channel Capacity and Description of Flooding which would occur shortly after channel capacity exceeded.

ID #	Overtopping CFS	Flooding Descrption
1	11099	Breakout on West Bank, DS Charcot, flow travels d/s, eventually flooding structures.
2	10286	Breakout on East Bank, US Charcot- flow moves downstream, eventually flooding homes.
3	3517	Mobile Home Park Begins to flood (via gap in levee/floodwalls);entire mobile home area eventually floods.
4	2533	Q=2533 cfs- Structure N Berryessa and West of Creek floods. Q = 4363 Auto Glass Shop floods.
5	5599	Structures along west side of Coyote, South of Berryessa, North of Maybury, bgein to flood.
6	9040	Parklng Lot on West side begins to flood; structures affected at ~11000 cfs
7	4084	Park to the west of Coyote Creek Begins to flood. Park overtops & floods structures eventually.
8	11510	Selma Park on E Bank of Coyote has filled up; flow goes down S 19th St to flood homes to the NW;Selma park begins flooding at 6613 cfs.
9	11510	Williams St Park on W Bank of Coyote has filled up; flow begins to flood structures to the NW.
10	7400	Rock Spring Neighboorhood starts to flood
11	11800	Tully Overtops
12	1000	Singleton Road Overtops (Less than 1000 CFS, starts the simulation inundated)
13	6700	Fontanoso Way Gap"" gap in floodwall protecting industrial park begins to flood
14	9870	Coyote Creek, North-West of Ogier Ponds floods, Coyote Valley Resort & RV, and some business on the creek side of Coyote begin flooding
15	5820	Scyamore Avenue that is protecting Santa Clara County Boy's Ranch overtops
16	5880	Sycamore Avenue Bridge
17	11870	Santa Clara County Justice Training Center begins to flood